

INDOOR AIR QUALITY

Mold Investigation at MSP

At the Minneapolis-St. Paul Airport, facility workers discovered suspected mold growth in a wall cavity during routine maintenance.

Field Environmental Consulting confirmed mold growth through testing and quantified impacted building materials.



Field Environmental Consulting developed a Scope of Work, coordinated subcontractors, supervised the remediation activities, and provided a report confirming the mold was abated.

All work was successfully completed without impacting the day-to-day operations of the client.